



2500 Wilson Boulevard, Arlington, Virginia 22201-3834 tel 703-907-7070 • fax 703-907-7549 • www.ec-central.org

October 23, 2006

ERRATA SHEET TO EIA-364-D

This Errata Sheet has been prepared to correct an error in the conversion table that compares MIL-STD-1344, method 1002.2 test conditions to EIA-364-31B test conditions listed in annex table B.1 as follows:

Change From:

031A	Condition A	1002.2	Condition A
031A	Condition B	1002.2	Condition B

Change To:

031A	Condition A	1002.2	Condition B
031A	Condition B	1002.2	Condition A

